



# INDIAN NOTICES TO MARINERS



EDITION NO. 10 DATED 16 MAY 2016

(CONTAINS NOTICES 114 TO 116)

REACH US 24 x 7



in的角度@navy.gov.in  
msis-inho@navy.gov.in



+91-135-2748373



National Hydrographic Office  
107-A, Rajpur Road  
Dehradun – 248001  
INDIA



Joint Director of Hydrography  
Maritime Safety Information Services  
+91- 135 - 2746290-117

**WWW**  
[www.hydrobharat.gov.in](http://www.hydrobharat.gov.in)

## CONTENTS

Section No.	Title
I	List of Charts Affected
II	Permanent Notices
III	Temporary and Preliminary Notices
IV	Marine Information
V	NAVAREA VIII Warnings in force
VI	Corrections to Sailing Directions
VII	Corrections to List of Lights
VIII	Corrections to List of Radio Signals
IX	Reporting of Navigational Dangers

(PUBLISHED ON NHO WEBSITE ON 1<sup>ST</sup> & 16<sup>TH</sup> OF EVERY MONTH)

**FEEDBACK:** [msis-inho@navy.gov.in](mailto:msis-inho@navy.gov.in)



INSIST ON INDIAN CHARTS AND  
PUBLICATIONS  
Original, Authentic and Up-to-Date



© Govt. of India Copyright

No permission is required to make copies of these Notices. However, such copies are not to be commercially sold.

## II

### MARINER'S OBLIGATION AND A CHART MAKER'S PLEA

Observing changes at sea proactively and reporting them promptly to the concerned charting agency, is an obligation that all mariners owe to the entire maritime community towards SOLAS. Mariners are requested to notify the Chief Hydrographer to the Government of India at the above mentioned address/fax number/ E mail address immediately on discovering new or suspected dangers to navigation, changes/defects pertaining to navigational aids, and shortcomings in Indian charts/publications. The Hydrographic Note [Form IH – 102] is a convenient form to notify such changes. Specimen form is attached at Section IX with this notice. Also visit our website for downloading and filling up instructions for Hydrographic Note.

**Chief Hydrographer  
to the Government of India**

### **WARNING AGAINST USE OF COUNTERFEIT PRODUCTS**

**All mariners are cautioned against the use of counterfeit copies of IN Charts and publications. Navigational Charts produced after 31 Oct 14 carry NHO crest as watermark on the reverse with backslip. Chart Agent's stamp is mandatory on all Charts.**

**Counterfeit products may have errors resulting in potential risks. The same are not approved by inspecting agencies and do not satisfy the carriage requirements of SOLAS chapter V.**

**Mariners are strongly advised not to use or encourage the use of counterfeit charts and publications. Failure to comply with the warning may invite legal action.**

### III

## **EXPLANATORY NOTES**

**Corrections to Charts and Publications.** Section I comprises List of Charts affected by the notices contained in this edition. Whereas sections II and III contain information for correcting the charts and publications. Mariners should insist on corrected charts from their chart distributors/agents.

- (a) Geographical positions given are in the horizontal datum of the current edition of the chart, unless otherwise stated.
- (b) Bearings are true, reckoned clockwise from 000° to 359°. Bearings to lights are from seaward.
- (c) Symbols referred to, are those shown on the chart 5020 (INT 1).
- (d) Alterations to depth contours, deletion of depths to make way for new detail, etc; are not normally mentioned, unless they have some navigational significance.
- (e) Blocks and notes, if any, accompanying the Notices in Sections II and III are placed after Section IX.

**Temporary and Preliminary Notices.** These are indicated by (T) and (P) respectively after the Notice number and are placed in Section III. SI Nos. of those in force are published quarterly on 01 Jan, 01 Apr, 01 Jul and 01 Oct, and their text is published in Annual Edition of Indian Notices to Mariners. They should be inserted in pencil, by the user, on receipt.

**Source of Information.** A star preceding the number of a Notice indicates that the notice is promulgated by INHO based on original information received.

**Sailing Directions.** Corrections for the Sailing Directions (Pilots) are given in Section VI.

**Lights.** Corrections to Indian List of Lights are given in Section VII, where affected Light List number is quoted.

- (a) These corrections should be incorporated as per instructions given on page XI of the List of Lights.
- (b) Such correction notices to list of lights may be published in either an earlier or a later Edition of N to M than the Edition containing the Notice to the chart correction.
- (c) The range of a light given is its nominal range. Its geographical range is given in parenthesis only if it is less than the nominal range.
- (d) A star indicates that the corresponding field is to be amended and all stars indicate that new light is to be inserted.

**Radio Signals.** The corrections in Section VIII should be cut and pasted in the appropriate volume of the List of Radio Signals.

**Radio Navigational Warnings.**

- (a) These are broadcast as serially numbered NAVAREA warnings by the concerned NAVAREA coordinator through GMDSS and Area Radio Broadcasts.
- (b) They contain important information affecting navigational safety, which cannot await the publication of the next edition of N to M.
- (c) It should be borne in mind that they may be based on reports which cannot always be verified before promulgation.
- (d) It is therefore necessary to be selective, and promulgate only the more important warnings to avoid over loading users; the less important information is included in the forthcoming edition of N to M or the Chart/publication concerned.

## IV

**Laws and Regulations.** While in the interest of the safety of shipping, the Hydrographic Office makes every endeavor to include in its publications details of the laws and regulations of all countries pertaining to navigation, it must be clearly understood: -

- (a) That no liability whatsoever can be accepted for failure to publish details of any particular law or regulation and
- (b) That publication of details of a law or regulation is solely for the safety and convenience of shipping and implies no recognition of the International validity of the law or regulation.

**Correction of Charts and Publications by the Users.** Notices to Mariners contain important information concerning safety of navigation at sea, hence, they should be used to keep the specified charts and publications up-to-date.

**Reliance on Charts and Associated Publications.** While every effort is made by the Hydrographic Office to ensure the accuracy of the information on Charts and Publications before they are published, it should be appreciated that it may not always be complete and up-to-date. The mariner must be the final judge for the reliance he can place on the information available, bearing in mind his particular circumstances, local pilotage guidance and judicious use of available navigational aids.

**Use of Global Positioning System (WGS 84) positions.**

- (a) The positions of hydrographic objects shown on some of the Indian charts and publications are in Everest datum. However, the positions of vessels obtained from Global Positioning System (GPS) are on World Geodetic System 1984 datum. There will always exist a difference in the position values obtained by visual fixing (Everest Datum) and GPS position (WGS 84 datum).
- (b) Wherever these differences have been ascertained, their average values are published as a Cautionary Note on the chart concerned, as shifts in Latitude and Longitude. Whilst plotting GPS positions on charts, the shift values as given on the chart must be applied, before making any assessment of the navigational situation vis-à-vis the other charted information.
- (c) These datum shift values are not uniform, particularly in areas off Andaman and Nicobar and Lakshadweep Islands, as these places are not linked to mainland network (Everest datum). Mariners are advised to use alternate source of position information such as Visual or Radar, particularly when closing the shore or navigating in the vicinity of dangers.

**Source Data on Charts.** All Indian charts contain specific information on their source of hydrographic data. In areas where the source data is very old, incomplete and less reliable, the mariner must use such charts with prudence. Mariner should always use the largest scale charts available for the area. Apart from being the most detailed, the larger scale charts are usually corrected first. Hydrographic information may be sparse on small scale charts. On such charts, a charted shoal may be in error as regards position, least depth and extent. Uncharted dangers may also exist, particularly in areas away from well-established routes. Mariners must exercise due caution.

**Further Guidance.** The Mariner's Hand Book (NP 100) gives full explanation on the use of charts and the type of information contained on charts. In their own interest, all users of charts should refer to it.

## NEWLY PUBLISHED INDIAN CHARTS, ENC'S AND PUBLICATION

1. The new Indian Charts that are available for mariners in the market is as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title, Limits &amp; Description</i>	<i>Scale</i>	<i>Folio</i>	<i>Price</i>
202	30-04-2016	<b>JAKHAU TO DWARKA LIMITS</b> 22° 04'.00N; 68° 06'.50E. 23° 20'.90N; 69° 00'.60E.	1,50,000	2	Rs. 1870.00
268 (INT 7353)	30-04-2016	<b>CENTRAL LAKSHADWEEP LIMITS</b> 09° 57'.00N; 71° 48'.00E. 11° 44'.00N; 74° 34'.00E.	3,00,000	4	Rs. 1870.00
401 (INT 7435)	15-04-2016	<b>PREPARIS ISLAND TO LANDFALL ISLAND LIMITS</b> 13° 37'.10N; 92° 57'.40E. 14° 56'.60N; 93° 50'.00E.	1,50,000	6	Rs. 1870.00
404 (INT 7439)	15-04-2016	<b>ELPHINSTONE HARBOUR TO PORT BLAIR LIMITS</b> 11° 33'.00N; 92° 05'.00E. 12° 24'.00N; 93° 25'.00E.	1,50,000	6	Rs. 1870.00
405 (INT 7440)	15-04-2016	<b>PORT BLAIR TO LITTLE ANDAMAN ISLAND LIMITS</b> 10° 52'.00N; 92° 05'.00E. 11° 43'.00N; 93° 37'.00E	1,50,000	6	Rs. 1870.00

2. The new edition Indian Charts that is available for mariners in the market is as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title, Limits &amp; Description</i>	<i>Scale</i>	<i>Folio</i>	<i>Price</i>
2010	30-04-2016	<b>KARWAR NAVAL HARBOUR LIMITS</b> 14° 42'.70N; 74° 05'.00E. 14° 47'.00N; 74° 11'.90E.	12,500	3	Rs. 1870.00

3. The Indian Charts permanently withdrawn are as follows:-

<i>Chart No.</i>	<i>Date of Publication</i>	<i>Title</i>	<i>On Publication of New Chart/ Edition</i>	<i>Date of Publication</i>
2010	31-06-2013	KARWAR NAVAL HARBOUR	2010	30-04-2016
202	31-02-2011	JAKHAU TO DWARKA	202	30-04-2016
268 (INT 7353)	31-12-2009	CENTRAL LAKSHADWEEP	268 (INT 7353)	30-04-2016
401	30-04-2003	PREPARIS ISLAND TO LANDFALL ISLAND	401 (INT 7435)	15-04-2016
404	31-07-2003	ELPHINSTONE HARBOUR TO PORT BLAIR	404 (INT 7439)	15-04-2016
405	15-07-2003	PORT BLAIR TO LITTLE ANDAMAN ISLAND	405 (INT 7440)	15-04-2016

## VI

4. The new Indian Electronic Navigational Charts that are available for mariners in the market is as follows:-

<i>ENC Cell Name</i>	<i>Chart No.</i>	<i>Title</i>	<i>Issue Date</i>
<b>IN2253EP</b>	<b>253</b>	<b>VERAVAL TO PIPAVAV</b>	<b>13-05-2016</b>

5. The Indian Electronic Navigational Charts that are permanently withdrawn are as follows:-

<i>ENC Cell Name</i>	<i>Chart No.</i>	<i>Title</i>	<i>Issue Date</i>
<b>IN2253VP</b>	<b>253</b>	<b>VERAVAL TO PIPAVAV</b>	<b>02-04-2013</b>
<b>IN42525A</b>	<b>2525</b>	<b>APPROACHES TO MANDA BAY</b>	<b>28-04-2016</b>

6. The forthcoming Indian Charts are as follows:-

<i>Chart No</i>	<i>Title</i>	<i>Scale</i>	<i>Remarks</i>
<b>2017</b>	<b>NAVLAKHI AND APPROACHES</b>	<b>25,000</b>	<b>New Chart</b>
<b>3017</b>	<b>APPROACHES TO DHAMRA RIVER</b>	<b>50,000</b>	<b>New Chart</b>
<b>4046</b>	<b>RANGAT BAY</b>	<b>10,000</b>	<b>New Chart</b>
<b>4013</b>	<b>APPROACHES TO LACAM HARBOUR</b>	<b>25,000</b>	<b>New Chart</b>
	<b>NEILL ISLAND PIER</b>	<b>10,000</b>	
	<b>LACAM HARBOUR</b>	<b>12,500</b>	
	<b>FUSILIER CHANNEL(NANCOWRY STRAIT)</b>	<b>25,000</b>	

### Availability of ENCs

The complete folios of Official Indian ENCs are distributed worldwide through JEPPESEN MARINE (formerly C-MAP), UKHO and Norwegian Hydrographic Service. UKHO distributes Indian ENCs through the world wide network of their agents and distributors. Updates are also made available as per the existing policy of the distributor. Mariners and other ENC users may contact the under mentioned for further details:

<b>United Kingdom Hydrographic Office</b> Admiralty Way, Taunton, Somerset TA1 2DN, UK Tel: +44 (0) 1823 337900 Fax: +44 (0) 1823 330561, 1823 284077 Telex: 46274 Web site: www.hydro.gov.uk	<b>M/s Jeppesen Norway AS</b> Hovalandsveien 52 PO Box 212, N-4379, Egersund, Norway Ph: +47 51 464700 Mob: +91 93222 38542 Fax: +47 51 464701 Email: enc@jeppesen.com, info@c-map.co.no Website: www.jeppesen.com
<b>M/s Primar</b> Norwegian Hydrographic Service, Postbox 60, 4001 Stavanger Norway Telephone - +47 - 51 85 87 00 Fax - + 47 - 51 85 87 08 E-mail: data@ecc.no Website: - www.primar.org	<b>M/s IIC Technologies Limited</b> B-2-350/5/B-22, Road No. 3 Banjara Hills Hyderabad- 500 034 Tel:+91 4039144444 Fax: +91 4039144455 Email: somnath.marthi@iictechnologies.com Web: www.iictechnologies.com

**SECTION – I**

The list of charts affected by the Notices 114 to 116 contained in this edition is as follows:

<b>CHART NUMBER</b>	<b>FOLIO NO.</b>	<b>NOTICE NO.</b>
213	3	115
214	3	115
217	3	116
257 (INT 7343)	3	115
258 (INT 7348)	3	116
272	4	116
293 (INT 7022)	3	115, 116
2043	3	115
2046	3	115
2052 (INT 7350)	3	116
2059 (INT 7322)	2	114



**SECTION – II**  
**PERMANENT NOTICES**

**\*114 (10/16) INDIA – WEST COAST – Kandla Sogal Channel – Legend.**

Source: NHO.

**Chart 2059 (INT 7322)** [previous update NC 30 Sep 15]

Amend Legend to; 344.5°–164.5° 22° 57′.52N., 70° 14′.45E.

**\*115 (10/16) INDIA – WEST COAST – Redi Anchorage – Wreck.**

Source: Maharashtra Maritime Board.

**Chart 293 (INT 7022)** [previous update 084/16]

Insert  PA 15° 46′.77N., 73° 36′.32E.

**Chart 257 (INT 7343)** [previous update 132/15]

Insert  PA 15° 46′.71N., 73° 36′.36E.

**Chart 213** [previous update 132/15]

Insert  PA 15° 46′.77N., 73° 36′.32E.

**Chart 214** [previous update 132/15]

Insert  PA 15° 46′.77N., 73° 36′.32E.

**Chart 2043** [previous update 132/15]

Insert  PA 15° 46′.77N., 73° 36′.32E.

**Chart 2046** [previous update 132/15]

Insert  PA 15° 46′.77N., 73° 36′.32E.

**\*116 (10/16) INDIA – WEST COAST – Approaches to Port of New Mangalore – Buoy.**

Source: IH-102, INS Makar.

**Chart 293 (INT 7022)** [previous update 115/16]

Delete  VQ(9).10s 12° 48′.80N., 74° 43′.50E.

**Chart 272** [previous update 090/15]

Delete  VQ(9).10s: 12° 48′.80N., 74° 43′.50E.

**Chart 258 (INT 7348)** [previous update 090/15]


Delete  VQ(9).10s: 12° 48′.73N., 74° 43′.55E.

**Chart 217** [previous update 090/15]

Delete  VQ(9).10s 12° 48′.73N., 74° 43′.55E.

**Chart 2052 (INT 7350)** [previous update 090/15]

Delete  VQ(9).10s 12° 48′.80N., 74° 43′.50E.



**SECTION – III**  
**TEMPORARY AND PRELIMINARY NOTICES**

**NIL**



## **SECTION – IV** **MARINE INFORMATION**

### 1. **NAVTEX TRANSMISSION**

Status of MSI Promulgation by NAVTEX Stations is as follows:-

Mumbai - Temporarily Out of Operation

Chennai - Temporarily Out of Operation

Mauritius (Cassis) - Operational

Seychelles (Mahe) – Operational

Following new Navtex stations along the Indian coast are operating on trial basis:-

<b>INTERNATIONAL NATIONAL NAVTEX FREQUENCY - 518 kHz</b>								
<b>Sl.</b>	<b>Station Name</b>	<b>B1</b>	<b>Broad Cast Timings in UTC</b>					
(a)	Veraval	H	0110	0510	0910	1310	1710	2110
(b)	Vengrula Point	J	0130	0530	0930	1330	1730	2130
(c)	Muttam Point	L	0150	0550	0950	1350	1750	2150
(d)	Porto Novo	O	0220	0620	1020	1420	1820	2220
(e)	Vakalpudi	Q	0240	0640	1040	1440	1840	2240
(f)	Balasore	S	0300	0700	1100	1500	1900	2300
(g)	Keating Point	V	0330	0730	1130	1530	1930	2330

### 2. **MISIDENTIFYING FISHING BOATS AS PIRATE SKIFFS**

All merchant vessels entering Indian EEZ are advised that dense fishing activity may be encountered off West Coast of India. Fishing is generally carried out by mechanized boats and single hull boats with outboard motors carrying 4-5 crew using long lines upto 50 NM from coast. The vessels traversing the nets are likely to be approached by fishing boats for safeguarding nets and lines and should not be mistaken as skiffs and PAG's. Masters of vessels to report any suspicious activity of fishing vessels immediately to MRCC (Mumbai) on telephone +91-22-24388065, 24316558, Email: - [indsar@vsnl.net](mailto:indsar@vsnl.net), or [icgmrc\\_mumbai@mtnl.net](mailto:icgmrc_mumbai@mtnl.net). Any suspicious activity of skiffs / boats to be photographed if possible. Merchant vessels with armed guards on board are to report presence of guards to Indian Navy/Coast Guard while transiting Indian EEZ.

(Source - NAVAREA VIII Warning 100/12)

### 3. **DISPLAY ANOMALIES IN ECDIS**

(a) Mariners are advised that the International Hydrographic Organization (IHO) check data set shows that some ECDIS systems fail to display some significant underwater features in the standard display mode. The use of this check data set, issued through ENC service providers and available from the IHO website [www.iho.int](http://www.iho.int), to check the operation of ECDIS is strongly recommended. JRC has confirmed that certain versions of JRC ECDIS fail to display some types of wreck and obstructions, including stranded wrecks, in any display mode.

Where JRC ECDIS is in use, paper charts should be the primary means of navigation until the ECDIS has been proved to operate correctly. See [www.jrc.co.jp/eng/product/marine/whatsnew/20120313/index.html](http://www.jrc.co.jp/eng/product/marine/whatsnew/20120313/index.html) for further information.

(b) Some Electronic Chart Display and Information Systems (ECDIS) may exhibit operating anomalies. The International Maritime Organization's (IMO) circular SN.1/CIRC.312 pages /imodocs.aspx (registration required) lists identified anomalies, Their characteristics and remedial advice. Mariners are reminded that they should access the International Hydrographic Organization (IHO) data presentation and performance check (DPPC) dataset (news links of <http://www.iho.int/srv1>) and ensure that all installed ECDIS units are checked.

(Source - NAVAREA VIII Warning 141/12 & 529/12)

#### **4. SAFETY FAIRWAYS, RECOMMENDED ROUTES, TRAFFIC SEPARATION SCHEME**

The Director General Shipping has established Safety fairways, recommended routes and traffic separation scheme (TSS) in restricted Indian waters including the offshore development area to enhance safety of navigation. The details of coordinates for the above have been published in the fortnightly Indian Notices to Mariners Edition No 14 of 2008 (16<sup>th</sup> July 2008).

(a) Safety Fairways: An area within which permits are not granted for the erection of oil or gas related structures. The use of a safety fairway is not usually mandatory, but is recommended. Safety fairways have been promulgated in and round offshore development area in Arabian Sea up to the Exclusive Economic Zone (EEZ) due to increased weather related marine accidents and dense traffic. These are mandatory for all Indian ships and vessels transiting through the ODA and recommendatory for all foreign flag ships and vessels irrespective of size.

(b) Recommended routes have been established along the coast of Gujarat. These are to assist mariners to navigate safely in order to represent the best routes for crossing traffic and to minimize head-on encounters in vicinity of Oilfield Development Areas and regulate coastal traffic. Mariners are advised to keep 1 to 2 miles starboard of the shown routes consistent with Rules of the Road.

(c) Traffic Separation Schemes (TSS). The TSS off Mumbai harbour is mandatory for all Indian and foreign flag ships and vessels entering and leaving Mumbai harbour and Jawaharlal Nehru Port Trust (JNPT)/ Nhava-Sheva harbour irrespective of size.

#### **5. GAGAN SYSTEM COMMISSIONED FOR OPERATIONS**

The GAGAN System is now commissioned for safety of life, civil aviation, and en- route operations in addition to all other non-aviation applications. The GAGAN signal is being broadcasted through GSAT-8 and GSAT-10 with PRN127 & 128 respectively.

All the GPS users are requested to enable SBAS functionality in their receivers, configure it to receive PRN-127& 128 and avail the benefits of GAGAN in terms of increased accuracy and reliability. There may be occasional signal outages due to system up-gradation activities.

#### **6. USAGE OF THURAYA/ IRRIDUM AND SATELLITE PHONE**

The use of Thuraya, Iridium and other such satellite phone is banned in India under Sec 6 of Indian Wireless Act and Sec 20 of Indian Telegraph Act. It is intimated to all shipping companies/ shipping agents that use of Thuraya/ Iridium and other such satellite phones are banned in Indian waters and seafarers should not use the same.

Satellite phones can be used only after no objections certificate issued by department of telecommunication (DOT) on a case to case basis. The shipping agents should mandatorily intimate the details of person carrying Thuraya and the particulars of Thuraya, Iridium and other such sets in pre arrival notification on security (PANS).

The unauthorized holders of Thuraya/ Iridium and other such Satellite phones can be prosecuted under Sec 6 of Indian Wireless Act and Sec 20 of Indian Telegraph Act.

#### **7. CAUTIONARY NOTE**

There is a finite amount of lag between publication of large and small scale Indian Nautical Charts. To avoid uncertainty the mariners are advised to use large scale charts for coastal navigation wherever applicable and available. In addition, mariners are to refer large scale charts in conjunction with small scale charts in areas where both overlap during both planning and conduct of passage.

**List of Indian Chart Agents**

<p><b>M/s OSA Books and Periodicals</b> R-246, Greater Kailash –I, New Delhi - 110 048 Tel/Fax: 011-46557337, Mob: 9971093992 Email: rpani246@gmail.com</p>	<p><b>M/s Sterling Book House</b> 181, Dr. DN Road, Fort, Mumbai – 400 001 Tel: 91-22-22612521, Fax: 91-22-22623551 Email : sbh@vsnl.com</p>
<p><b>M/s Global Charts &amp; Nav. Aids Pvt. Limited</b> 1A, Goa Mansion, Ground Floor, 58, Dr. Sunderlal Bahl Path (Goa Street), Fort, Mumbai - 400 001 Tel: 91-22-22626318, 22626380 Fax: 91-22-22621488 Email: sales@globalcharts.in Web: www.globalcharts.com.sg</p>	<p><b>EW Liner Charts &amp; Publication (India)</b> 2/524, Sundeep Road, Chinna Neelangarai, Chennai 600041 Tele/Fax : +91-44-24490668 Mob No : +91-9003245348 Email: maritimeindia@airtelmail.in</p>
<p><b>M/s C &amp; C Marine Combine</b> 25 Bank Street, 1<sup>st</sup> Floor, Mumbai - 400 023 Tel: 91-22- 22660525, 22661937, 22672143 Fax: 91-22-22670896 Email: ccmarine@vsnl.com, sales@ccmarine.in</p>	<p><b>Gujarat Pipavav Port Limited</b> PO – Ucchaiya, Dist – Amereli, Gujarat – 365 560 Tele: +91- 2794302400 Fax: 302413 (Only for Pipavav Port Chart)</p>
<p><b>M/s SVR Chart Agencies</b> Door No.50-81-35/6, Santhipuram, Seetammapeta, Visakhapatnam – 530 016 Tele Fax: 0891-2799471, Cell: +91 9440132553, 9849120988, 9885308200 Email : mahalakshmitravels@hotmail.com</p>	<p><b>M/s Jeppesen India Pvt. Ltd</b> 505, Raheja Arcade, Sector 11 CBD, Belapur, Navi Mumbai – 400 614 Tel: +91 22 6510 3668, Fax: +91 22 55939504 Mob: +9322238542 Email: RajShekhar.Chakravorty@jeppesen.com, info@jeppesen.com Website: www.jeppesen.com</p>
<p><b>M/s JM Maritime Services</b> 24/24C Kavarana Building, Ground Floor, Wadi Bunder, P.D. Mellow Road, Mumbai – 400 009 Tel: +91 22 23736956, Fax: 022 - 23725083 Cell: +91 9820788357 Email : jmms@mtnl.net.in, charts@mtnl.net.in</p>	<p><b>M/s Global Marine Infratech Pvt. Ltd.</b> Siksha Sandan, Ground Floor, ND-7, Bhubaneswar – 751015 Tel: +91-674-2550599, Fax: +91-674-2551899 Cell:- +919937064299 Email: ashiskantha@gmiindia.in Web: www.gmiindia.in</p>
<p><b>Lift o Marine</b> Paper / Digital Charts Allen’s Mansion, Flat C6 Nungi Station Road Kolkata – 700 140, IN Tel: +91 9836972027 / 8902228463 Fax: 033 24924283 Email: sankar@liftmarine.org Web: www.liftmarine.org</p>	<p><b>M/s L. R. Marine Services</b> 301, 3rd Floor, Birya House, 265, Perin Nariman Street, Fort, Mumbai - 400 001. Tel: +91-22-2269 1535, Fax: +91-22-6635 9148 Cell No: +91 8108926880/ +91 98214 60258 Email: lrcharts@gmail.com, lrmarine@live.com</p>
<p><b>M/s Engineering Logistics Executive Multi Services</b> Elems Charts, Door No: 61-4-45-A/4, Prakash Nagar Malkapuram Visakhapatnam – 530 011 Mob: +91 9133871827 Email: sales@elemscharts.in Web: www.elemscharts.in</p>	<p><b>M/s IIC Technologies Limited</b> B-2-350/5/B-22, Road No. 3, Banjara Hills, Hyderabad – 500 034 Tel: +91 4039144444 Fax: +91 4039144455 Email: somnath.marthi@iictechnologies.com Web: www.iictechnologies.com</p>
<p><b>M/s Aatash Computer &amp; Communications Pvt. Ltd.</b> 213, Devarc Commercial Complex Nr. Iscom Circle (above Woodland Showroom) S. G. Highway Ahmedabad – 380 015 Mob: +91 7926923982 Email: jyoti@aatash.com, zubin@aatash.com</p>	<p><b>M/s Zenith Surveys (I) Pvt. Ltd.</b> Lakhani’s Plam View, First Floor, Office No. 889, Sector 48, Nerul, Navi Mumbai – 400 706 Tel/ Fax: +91-22- 27708011 Email: zenithsurveys703@gmail.com, nyvmane@yahoo.com Web: www.zenithsurvey.com</p>

<p><b>M/s VDO Marine Instruments</b> Shanghar Building, PO Bag No – 645, 45/271, Corner of Bristow &amp; Naval Road, Willingdon Island, Kochi – 682 003 Tel: +91 484 2667157 Fax: +91 484 2667121 Email: atmain@md4.vsnl.net.in</p>	
---	--



**SECTION – V**  
**NAVAREA – VIII WARNINGS IN FORCE**

1. For details of NAVAREA limits and organisation/coordination, please refer to Notice No. 12 of the Special edition of Indian Notice to Mariners – 2012.

2. NAVAREA VIII Warnings in force as on 15 Apr 16:

**2015 SERIES** – 287 334 386 445 486 498 633 646 735

**2016 SERIES** – 031 064 190 249 256 258 276 295 305 309 310 312 313 314 318 319 324 326 327  
328 331 332 333 334 335 336 337 338 339 340

3. NAVAREA VIII Warnings issued during the period from 01 May to 15 May 16 (both dates inclusive) are as tabulated below:–

<b>317.</b>	<b>Cancel NAVAREA VIII MSG 311 and this MSG.</b>
<b>318.</b>	<b>India East Coast – off Gopalpur.</b> Charts 31 352 353 3005 INT 706. Army air defence firing and BPTA flight scheduled daily from 10-11, 18-20, 30-31 May and 01 Jun 16 from 0130 -0730 and 0830 - 1430 UTC.
2.	Firing area bounded by (a) 19-14.60N 084-53.70E (b) 19-07.39N 085-35.94E (c) 18-33.61N 084-53.74E and arc of 41 NM radius joining point b and c. Safe flying Ht 6.1 KM.
3.	Flight area bounded by 19-17.67N 084-55.21E, 19-10.75N 084-47.38E, 18-56.03N 084-52.64E, 19-12.33N 085-14.92E. Safe flying Ht 1.5 KM.
4.	Cancel this MSG 011530 UTC Jun 16.
<b>319.</b>	<b>India West Coast – Mumbai ODA.</b> Charts 255 INT 71. MV Albatross progressing survey till 15 May 16 from 19-15.9N 072-06.0E to 19-12.8N 072-06.7E and 19-15.9N 072-06.0E to 19-12.8N 072-06.6E.
2.	Wide berth requested.
3.	Cancel this MSG 151829 UTC May 16.
<b>320.</b>	<b>India West Coast – off Tapti ODA.</b> Charts 21 210 INT 71. Firing by CG aircraft scheduled on 11, 12, 17, 29 May 16 from 0330-1130 UTC in area bounded by 20-18.5N 072-02.5E, 20-18.5N 072-12.5E, 20-09.5N 072-10.0E, 20-09.5N 072-00.0E. Safe flying Ht 2 KM.
2.	Cancel this MSG 291230 UTC May 16.
<b>321.</b>	<b>India West Coast.</b> Charts 271 292 INT 71. Rig list correct at 051003 UTC Apr 16.
	ABAN ICE 22-29.58N 068-07.56E
	ABAN III 19-29.98N 071-16.28E
	ABAN IV 18-29.15N 072-15.11E
	CE THORNTON 19-40.10N 072-18.89E
	DISCOVERY-1 20-18.78N 072-02.12E NEW
	DYNAMIC VISION 22-18.69N 068-34.46E
	DEEP SEA FORTUNE 19-40.14N 072-00.34E
	DEEP SEA FOSSIL 19-17.71N 071-24.33E
	FG MCCLINTOCK 19-37.33N 071-19.97E NEW
	GREAT DRILL CHAAYA 18-39.26N 070-58.87E NEW
	GREAT DRILL CHETNA 18-49.13N 071-16.33E NEW
	GREAT DRILL CHAARU 20-07.04N 071-49.35E
	HARVEY H WARD 18-48.40N 072-20.00E
	JINDAL STAR 19-28.40N 071-12.60E
	JT ANGEL 22-25.98N 068-33.14E
	MERCURY FOCUS 21-18.12N 072-31.64E
	NOBLE ED HOLT 19-01.90N 071-32.57E
	PARAGON L-786 19-29.88N 071-24.70E
	PARAGON M 1161 19-28.98N 071-19.63E
	PARAMESWARA 20-04.98N 071-59.67E
	RON TAPMEYAR 19-24.01N 071-15.33E NEW
	SAGAR GAURAV 20-20.45N 071-15.40E
	SAGAR SHAKTI 19-37.86N 071-23.28E
	SAGAR JYOTI 19-07.74N 072-02.61E
	SAGAR KIRAN 19-19.64N 071-16.56E NEW
	SAGAR LAXMI 20-58.00N 071-33.00E
	SAGAR PRAGATI 20-58.00N 071-33.00E
	SAGAR UDAY 19-06.54N 071-22.35E
	TRIDENT II 18-50.59N 072-13.00E
	TRIDENT XII 19-31.69N 071-16.51E
	VICTORY DRILLER 18-31.95N 072-15.23E
	VIRTUE-I 19-26.06N 071-24.26E
	VALIANT DRILLER 19-33.13N 071-16.35E
2.	Wide berth requested.
3.	Cancel NAVAREA VIII MSG 262.

<b>322.</b>	<b>Cancel NAVAREA VIII MSG 027 228 and this MSG.</b> INTM 052 refers.																																																																		
<b>323.</b>	<p><b><u>NAVAREA VIII warnings in force as on 06 May 16</u></b>  <b><u>2015 Series</u></b> – 287 334 386 445 486 498 633 646 735  <b><u>2016 Series</u></b> – 031 063 064 190 237 249 256 258 269 272 276 290 291 295 303 305 308 309  310 312 313 314 318 319 320 321 322 323</p> <p>(a) NAVAREA VIII warnings less than 42 days promulgated via SafetyNet.  (b) Text of NAVAREA VIII warnings inforce including those which no longer broadcast available in www.hydrobharat.nic.in.  (c) Cancel this MSG 131000 UTC May 16.</p>																																																																		
<b>324.</b>	<p><b>Bay of Bengal - West of Preparis Island.</b> Charts 371 INT 706. MV Polarcus Asima will progress survey from 10 May to 05 Jun 16 in area bounded by 15-25N 092-09E, 14-39N 092-09E, 14-39N 093-21E, 15-25N 093-21E.</p> <p>2. Wide berth of 06 NM requested.  3. Cancel NAVAREA VIII MSG 290 and this MSG 051829 UTC Jun 16.</p>																																																																		
<b>325.</b>	<p><b>India West Coast.</b> Charts 271 292 INT 71. Rig list correct at 091002 UTC May 16.</p> <table> <tr><td>ABAN ICE</td><td>22-29.58N 068-07.56E</td></tr> <tr><td>ABAN III</td><td>19-29.98N 071-16.28E</td></tr> <tr><td>ABAN IV</td><td>18-29.15N 072-15.11E</td></tr> <tr><td>CE THORNTON</td><td>19-40.10N 072-18.89E</td></tr> <tr><td>DISCOVERY-1</td><td>20-18.78N 072-02.12E</td></tr> <tr><td>DYNAMIC VISION</td><td>22-18.69N 068-34.46E</td></tr> <tr><td>DEEP SEA FORTUNE</td><td>19-40.14N 072-00.34E</td></tr> <tr><td>DEEP SEA FOSSIL</td><td>19-17.71N 071-24.33E</td></tr> <tr><td>FG MCCLINTOCK</td><td>19-37.33N 071-19.97E</td></tr> <tr><td>GREAT DRILL CHAAYA</td><td>18-39.26N 070-58.87E</td></tr> <tr><td>GREAT DRILL CHETNA</td><td>18-49.13N 071-16.33E</td></tr> <tr><td>GREAT DRILL CHAARU</td><td>20-07.04N 071-49.35E</td></tr> <tr><td>HARVEY H WARD</td><td>18-48.40N 072-20.00E</td></tr> <tr><td>JINDAL STAR</td><td>19-28.40N 071-12.60E</td></tr> <tr><td>JT ANGEL</td><td>22-25.98N 068-33.14E</td></tr> <tr><td>MERCURY FOCUS</td><td>21-18.12N 072-31.64E</td></tr> <tr><td>NOBLE ED HOLT</td><td>19-01.90N 071-32.57E</td></tr> <tr><td>PARAGON L-786</td><td>19-29.88N 071-24.70E</td></tr> <tr><td>PARAGON M 1161</td><td>19-28.98N 071-19.63E</td></tr> <tr><td>PARAMESWARA</td><td>20-04.98N 071-59.67E</td></tr> <tr><td>RON TAPMEYAR</td><td>19-24.01N 071-15.33E</td></tr> <tr><td>SAGAR GAURAV</td><td>20-20.45N 071-15.40E</td></tr> <tr><td>SAGAR SHAKTI</td><td>19-37.86N 071-23.28E</td></tr> <tr><td>SAGAR JYOTI</td><td>19-07.74N 072-02.61E</td></tr> <tr><td>SAGAR KIRAN</td><td>19-19.64N 071-16.56E</td></tr> <tr><td>SAGAR LAXMI</td><td>20-58.00N 071-33.00E</td></tr> <tr><td>SAGAR PRAGATI</td><td>20-58.00N 071-33.00E</td></tr> <tr><td>SAGAR UDAY</td><td>19-06.54N 071-22.35E</td></tr> <tr><td>TRIDENT II</td><td>18-29.25N 072-14.43E NEW</td></tr> <tr><td>TRIDENT XII</td><td>19-31.69N 071-16.51E</td></tr> <tr><td>VICTORY DRILLER</td><td>18-31.95N 072-15.23E</td></tr> <tr><td>VIRTUE-I</td><td>19-26.06N 071-24.26E</td></tr> <tr><td>VALIANT DRILLER</td><td>19-33.13N 071-16.35E</td></tr> </table> <p>2. Wide berth requested.  3. Cancel NAVAREA VIII MSG 321.</p>	ABAN ICE	22-29.58N 068-07.56E	ABAN III	19-29.98N 071-16.28E	ABAN IV	18-29.15N 072-15.11E	CE THORNTON	19-40.10N 072-18.89E	DISCOVERY-1	20-18.78N 072-02.12E	DYNAMIC VISION	22-18.69N 068-34.46E	DEEP SEA FORTUNE	19-40.14N 072-00.34E	DEEP SEA FOSSIL	19-17.71N 071-24.33E	FG MCCLINTOCK	19-37.33N 071-19.97E	GREAT DRILL CHAAYA	18-39.26N 070-58.87E	GREAT DRILL CHETNA	18-49.13N 071-16.33E	GREAT DRILL CHAARU	20-07.04N 071-49.35E	HARVEY H WARD	18-48.40N 072-20.00E	JINDAL STAR	19-28.40N 071-12.60E	JT ANGEL	22-25.98N 068-33.14E	MERCURY FOCUS	21-18.12N 072-31.64E	NOBLE ED HOLT	19-01.90N 071-32.57E	PARAGON L-786	19-29.88N 071-24.70E	PARAGON M 1161	19-28.98N 071-19.63E	PARAMESWARA	20-04.98N 071-59.67E	RON TAPMEYAR	19-24.01N 071-15.33E	SAGAR GAURAV	20-20.45N 071-15.40E	SAGAR SHAKTI	19-37.86N 071-23.28E	SAGAR JYOTI	19-07.74N 072-02.61E	SAGAR KIRAN	19-19.64N 071-16.56E	SAGAR LAXMI	20-58.00N 071-33.00E	SAGAR PRAGATI	20-58.00N 071-33.00E	SAGAR UDAY	19-06.54N 071-22.35E	TRIDENT II	18-29.25N 072-14.43E NEW	TRIDENT XII	19-31.69N 071-16.51E	VICTORY DRILLER	18-31.95N 072-15.23E	VIRTUE-I	19-26.06N 071-24.26E	VALIANT DRILLER	19-33.13N 071-16.35E
ABAN ICE	22-29.58N 068-07.56E																																																																		
ABAN III	19-29.98N 071-16.28E																																																																		
ABAN IV	18-29.15N 072-15.11E																																																																		
CE THORNTON	19-40.10N 072-18.89E																																																																		
DISCOVERY-1	20-18.78N 072-02.12E																																																																		
DYNAMIC VISION	22-18.69N 068-34.46E																																																																		
DEEP SEA FORTUNE	19-40.14N 072-00.34E																																																																		
DEEP SEA FOSSIL	19-17.71N 071-24.33E																																																																		
FG MCCLINTOCK	19-37.33N 071-19.97E																																																																		
GREAT DRILL CHAAYA	18-39.26N 070-58.87E																																																																		
GREAT DRILL CHETNA	18-49.13N 071-16.33E																																																																		
GREAT DRILL CHAARU	20-07.04N 071-49.35E																																																																		
HARVEY H WARD	18-48.40N 072-20.00E																																																																		
JINDAL STAR	19-28.40N 071-12.60E																																																																		
JT ANGEL	22-25.98N 068-33.14E																																																																		
MERCURY FOCUS	21-18.12N 072-31.64E																																																																		
NOBLE ED HOLT	19-01.90N 071-32.57E																																																																		
PARAGON L-786	19-29.88N 071-24.70E																																																																		
PARAGON M 1161	19-28.98N 071-19.63E																																																																		
PARAMESWARA	20-04.98N 071-59.67E																																																																		
RON TAPMEYAR	19-24.01N 071-15.33E																																																																		
SAGAR GAURAV	20-20.45N 071-15.40E																																																																		
SAGAR SHAKTI	19-37.86N 071-23.28E																																																																		
SAGAR JYOTI	19-07.74N 072-02.61E																																																																		
SAGAR KIRAN	19-19.64N 071-16.56E																																																																		
SAGAR LAXMI	20-58.00N 071-33.00E																																																																		
SAGAR PRAGATI	20-58.00N 071-33.00E																																																																		
SAGAR UDAY	19-06.54N 071-22.35E																																																																		
TRIDENT II	18-29.25N 072-14.43E NEW																																																																		
TRIDENT XII	19-31.69N 071-16.51E																																																																		
VICTORY DRILLER	18-31.95N 072-15.23E																																																																		
VIRTUE-I	19-26.06N 071-24.26E																																																																		
VALIANT DRILLER	19-33.13N 071-16.35E																																																																		
<b>326.</b>	<p><b>India West Coast – South-East of Tapti ODA.</b> Charts 21 210 INT 71. Firing by CG aircraft scheduled on 11, 12, 17, 29 May 16 from 0330-1130 UTC in danger area bounded by 20-13.3N 071-59.0E, 20-13.3N 072-08.0E, 20-06.0N 072-06.9E, 20-06.0N 071-57.7E. Safe flying Ht 2 KM.</p> <p>2. Cancel NAVAREA VIII MSG 320 and this MSG 291230 UTC May 16.</p>																																																																		
<b>327.</b>	<p><b>India East Coast – North Bay of Bengal.</b> Charts 31 351 352 INT 71. Experimental flight trials scheduled from ITR from 14-16 May 16 from 0130-0530 UTC in danger zone bounded by 21-27.30N 087-30.55E, 19-42.63N 086-23.27E, 18-37.32N 087-55.38E, 20-21.12N 089-00.30E.</p> <p>2. Cancel this MSG 160630 UTC May 16.</p>																																																																		
<b>328.</b>	<p><b>India West Coast – Lakshadweep Sea.</b> Charts 21 272 INT 71. RV MGS Sagar progressing survey till 31 May 16 in areas bounded by (a) 13-00.7N 072-48.9E, 12-59.8N 072-01.5E, 13-59.7N 072-02.0E, 13-26.9N 072-38.9E (b) 12-36.9N 074-06.9E, 12-25.7N 074-16.8E, 11-11.0N 074-57.0E, 11-10.9N 074-08.1E.</p> <p>2. Wide berth requested.  3. Cancel this MSG 311829 UTC May 16.</p>																																																																		
<b>329.</b>	<p><b>India West Coast.</b> Charts 271 292 INT 71. Rig list correct at 101004 UTC May 16.</p> <table> <tr><td>ABAN ICE</td><td>22-29.58N 068-07.56E</td></tr> <tr><td>ABAN III</td><td>19-29.98N 071-16.28E</td></tr> <tr><td>ABAN IV</td><td>18-29.15N 072-15.11E</td></tr> <tr><td>CE THORNTON</td><td>19-40.10N 072-18.89E</td></tr> </table>	ABAN ICE	22-29.58N 068-07.56E	ABAN III	19-29.98N 071-16.28E	ABAN IV	18-29.15N 072-15.11E	CE THORNTON	19-40.10N 072-18.89E																																																										
ABAN ICE	22-29.58N 068-07.56E																																																																		
ABAN III	19-29.98N 071-16.28E																																																																		
ABAN IV	18-29.15N 072-15.11E																																																																		
CE THORNTON	19-40.10N 072-18.89E																																																																		

<b>329. Continued.</b>	
DISCOVERY-1	20-18.78N 072-02.12E
DYNAMIC VISION	22-18.69N 068-34.46E
DEEP SEA FORTUNE	19-40.14N 072-00.34E
DEEP SEA FOSSIL	19-17.71N 071-24.33E
FG MCCLINTOCK	19-37.33N 071-19.97E
GREAT DRILL CHAAYA	18-39.26N 070-58.87E
GREAT DRILL CHETNA	18-49.13N 071-16.33E
GREAT DRILL CHAARU	20-07.04N 071-49.35E
HARVEY H WARD	18-34.57N 072-16.74E NEW
JINDAL STAR	19-28.40N 071-12.60E
JT ANGEL	22-25.98N 068-33.14E
MERCURY FOCUS	21-18.12N 072-31.64E
NOBLE ED HOLT	19-01.90N 071-32.57E
PARAGON L-786	19-29.88N 071-24.70E
PARAGON M 1161	19-28.98N 071-19.63E
PARAMESWARA	20-04.98N 071-59.67E
RON TAPMEYAR	19-24.01N 071-15.33E
SAGAR GAURAV	20-20.45N 071-15.40E
SAGAR SHAKTI	19-37.86N 071-23.28E
SAGAR JYOTI	19-07.74N 072-02.61E
SAGAR KIRAN	19-19.64N 071-16.56E
SAGAR LAXMI	20-58.00N 071-33.00E
SAGAR PRAGATI	20-58.00N 071-33.00E
SAGAR UDAY	19-06.54N 071-22.35E
TRIDENT II	18-29.25N 072-14.43E
TRIDENT XII	19-31.69N 071-16.51E
VICTORY DRILLER	18-31.95N 072-15.23E
VIRTUE-I	19-26.06N 071-24.26E
VALIANT DRILLER	19-33.13N 071-16.35E
2.	Wide berth requested.
3.	Cancel NAVAREA VIII MSG 325.
<b>330. Cancel NAVAREA VIII MSG 63 and this.</b>	
<b>331. India West Coast – Central Arabian Sea.</b>	Charts 293 INT 71. CS Dependable will lay cables from 11-20 May 16 along route joining 18-44.0N 072-09.7E, 18-35.2N 072-08.6E, 18-20.0N 072-06.6E, 18-07.9N 072-05.2E, 17-55.9N 072-03.7E, 17-49.1N 072-02.8E, 17-43.7N 072-01.2E, 17-24.5N 071-52.2E, 17-14.4N 071-47.6E, 17-06.9N 071-44.1E.
2.	Wide berth requested.
3.	Cancel this MSG 201829 UTC May 16.
<b>332. NE Indian Ocean.</b>	Charts INT 71. Sri Lankan fishing vessel Dilruk Putha 08 reported adrift 02-38N 086-18E at 110400 UTC May 16.
2.	Cancel this MSG 141000 UTC May 16.
<b>333. India West Coast.</b>	Charts 271 292 INT 71. Rig list correct at 121001 UTC May 16.
ABAN ICE	22-29.58N 068-07.56E
ABAN III	19-29.98N 071-16.28E
ABAN IV	18-29.15N 072-15.11E
CE THORNTON	19-40.10N 072-18.89E
DISCOVERY-1	20-18.78N 072-02.12E
DYNAMIC VISION	19-11.03N 072-11.12E NEW
DEEP SEA FORTUNE	19-34.59N 071-23.43E NEW
DEEP SEA FOSSIL	19-20.38N 071-25.41E NEW
FG MCCLINTOCK	19-37.33N 071-19.97E
GREAT DRILL CHAAYA	18-39.26N 070-58.87E
GREAT DRILL CHETNA	18-49.13N 071-16.33E
GREAT DRILL CHAARU	20-07.04N 071-49.35E
GREAT DRILL CHITRA	18-48.14N 070-52.15E NEW
HARVEY H WARD	18-34.57N 072-16.74E
JINDAL STAR	19-28.40N 071-12.60E
JT ANGEL	22-25.98N 068-33.14E
MERCURY FOCUS	21-18.12N 072-31.64E
NOBLE ED HOLT	20-11.31N 071-52.15E NEW
PARAGON L-786	19-29.88N 071-24.70E
PARAGON M 1161	19-18.33N 071-27.31E NEW
PARAMESWARA	20-04.98N 071-59.67E
RON TAPMEYAR	19-24.01N 071-15.33E
SAGAR GAURAV	19-11.12N 071-33.22E NEW
SAGAR SHAKTI	19-37.86N 071-32.28E NEW
SAGAR JYOTI	19-07.74N 072-02.61E
SAGAR KIRAN	19-19.64N 071-16.56E
SAGAR LAXMI	20-58.00N 071-33.00E

<b>333. Continued.</b>	SAGAR PRAGATI	20-58.00N 071-33.00E
	SAGAR UDAY	19-06.54N 071-22.35E
	TRIDENT II	18-29.25N 072-14.43E
	TRIDENT XII	19-31.69N 071-16.51E
	VICTORY DRILLER	18-31.95N 072-15.23E
	VIRTUE-I	19-26.06N 071-24.26E
	VALIANT DRILLER	19-33.13N 071-16.35E
2.	Wide berth requested.	
3.	Cancel NAVAREA VIII MSG 329.	
<b>334. India West Coast - off Trivandrum.</b>	Charts 22 222 INT 71. Rocket launch from Thumba (08-31.98N 076-52.05E) scheduled from 0530-0730 UTC on 18 May 16.	
2.	Danger zone	
	(a)	Sector of radius 05 NM from Thumba between azimuth 190 and 300.
	(b)	Sector of radii 45 and 75 NM from Thumba between azimuth 220 and 260.
3.	Cancel this MSG 180830 UTC May 16.	
<b>335. India West Coast – off Ratnagiri.</b>	Charts 22 293 256 INT 71. Firing by Naval ships scheduled on 17 and 18 May 16 from 1030-1230 UTC in danger area bounded by 16-55N 071-55E, 16-55N 072-30E, 17-30N 072-30E, 17-30N 071-55E.	
2.	Cancel this MSG 181330 UTC May 16.	
<b>336. India East Coast – North Bay of Bengal.</b>	Charts 31 351 352 INT 71. Experimental flight trial scheduled from ITR on 18 and 19 May 16 from 0230-0630 UTC in danger zone bounded by 21-22.25N 086-55.73E, 21-08.94N 086-52.66E, 18-39.62N 088-15.68E, 19-23.71N 089-18.63E, 21-21.78N 087-10.85E, 21-22.69N, 086-56.35E.	
2.	Cancel this MSG 190730 UTC May 16.	
<b>337. Andaman Sea – South of Barren I.</b>	Charts 41 473 INT 71. Firing practice scheduled on 19 and 20 May 16 from 0430-0930 UTC in danger area bounded by 11-50N 093-40E, 11-50N 094-20E, 12-00N 093-40E, 12-00N 094-20E. Safe flying Ht 5 KM.	
2.	Cancel this MSG 201030 UTC May 16.	
<b>338. Andaman Sea – East I.</b>	Chart 4031 INT 71. DGPS (13-38N 093-03E) off on 15 May 16 from 0230-1030 UTC.	
2.	Cancel this MSG 151130 UTC May 16.	
<b>339. NAVAREA VIII Warnings in Force as on 13 May 16</b>		
	<b>2015 Series</b> – 287 334 386 445 486 498 633 646 735	
	<b>2016 Series</b> – 031 064 190 249 256 258 276 295 305 309 310 312 313 314 318 319 324 326 327 328 331 332 333 334 335 336 337 338	
(a)	NAVAREA VIII warnings less than 42 days promulgated via SafetyNet.	
(b)	Text of NAVAREA VIII warnings in force including those which no longer broadcast available in <a href="http://www.hydrobharat.nic.in">www.hydrobharat.nic.in</a> .	
(c)	Cancel this MSG 201000 UTC May 16.	
<b>340. Indian Ocean - NW of Albatross I.</b>	Charts INT 71. Craft Aquilla reported adrift since 12 May 16 in vicinity of 15-00S 057-27E.	
2.	Cancel this MSG 161000 UTC May 16.	

**SECTION – VI**  
**CORRECTIONS TO SAILING DIRECTIONS (PILOTS)**

**NIL**

**SECTION – VII**  
**CORRECTIONS TO LIST OF LIGHTS**

No	Name & Location	Position (Lat-Long)	Characteristics	Ht. mts	Range miles	Structure & Height (mts)	Remarks
D7402.4	Deleted; remove from list						
F1056.4	Cox's Bazar	21 26.06 N 91 58.32 E	Fl W 15s	54	21	Orange dome on framework tower 7	fl 0.7
-	-	..	Racon	..	..	..	ILRS Vol 2 Station 79330 *
F1836.7	- Bunguran. Tg Senubing	03 57.67 N 108 24.25 E	Fl W 4s	88	26	White metal framework tower 30	fl 0.5 *

**SECTION – VIII**  
**CORRECTION TO LIST OF RADIO SIGNALS**

**INP 31(1), 2014**

*(Last correction: Edition No. 09 dated 01 May 2016)*

NIL

**INP 31(2), 2014**

*(Last correction: Edition No. 09 dated 01 May 2016)*

**RADAR BEACONS**

**PAGE 10, SAUDI ARABIA (Red Sea Coast),**  
above **75910 Al Qdiamah.**  
Insert

<b>Shi'b Nazar Lt</b>	22°19'.40N 38°51'.32E					<b>M</b>		<b>75900</b>
-----------------------	-----------------------	--	--	--	--	----------	--	--------------

*(Source: BA 17/16)*

*(10/16)*

**INP 31(5), 2011**

*(Last correction: Edition No. 09 dated 01 May 2016)*

NIL

**INP 31(6), 2012**

*(Last correction: Edition No. 06 dated 16 Mar 2016)*

**PAGE 56, INDIA, MUNDRA, Pilots and Port,**  
**CONTACT DETAILS, Port:**  
*Delete VHF Channel and replace by;*

VHF Channel: Primary 77  
Secondary 73

*(Source: Adani Ports and SEZ Ltd. Mundra)*

*(10/16)*

**SECTION – IX**  
**CORRECTIONS TO MISCELLANEOUS NAUTICAL PUBLICATIONS**

**Indian Notices to Mariners, Special Edition-2012**

**Special Notice No. 16(Page 148)**

**(Source: NIOT - Chennai)**

Article 8 **Buoy Locations.**

**ARABIAN SEA MET OCEAN BUOY LOCATIONS**

AD04

Delete and replace by,

AD04

08°00'.00 N

73°00'.00E

## **SECTION – X** **REPORTING OF NAVIGATIONAL DANGERS**

### **Appeal to all Mariners**

1. Mariners at sea whilst on passage, or whilst entering / leaving ports / harbours and other waterways, are requested to look out for new or suspected dangers to navigation, changes in aids to navigation, or corrections to published charts and Sailing Directions. Whenever any such changes / dangers are observed, mariners are requested to notify the same to the Chief Hydrographer to the Government of India at the following address: -

National Hydrographic Office  
107-A, Rajpur Road,  
Dehradun - 248001  
(UTTARAKHAND), INDIA  
e-mail: - inho@navy.gov.in, msis-inho@navy.gov.in  
Fax No.: +91-135- 2748373  
WEB: www.hydrobharat.gov.in

### **Instructions for filling up IH 102**

2. Kindly follow the instructions below in order to help the Hydrographic Office (the recipient) to quickly issue NAVAREA warning / Notice to Mariners for the benefit of all other mariners at sea.

### **Position Reporting**

3. Accurate position or knowledge of position error is of great importance. Latitude and Longitude should only be used to specify position details when they have been fixed by GPS or Astronomical Observations. A full description of the method, equipment, time and datum (WGS 84/Everest/Other) used should be given. When position is defined by sextant angles or bearings (true or magnetic to be specified), more than two bearings should be used in order to provide a redundancy check. Distances observed by Radar should be corrected for index errors. Where position is derived after the event, from other observations and/or Dead Reckoning, the methodology of deriving the position should be included.

4. Paper Charts. A copy/tracing of largest scale chart is the best medium for forwarding details, the alterations and additions being shown thereon in red, but adequate details from the chart must be traced in black ink to enable the amendments to be fitted correctly.

5. ENCs. A Screen shot of largest scale usage band ENC with the alterations and additions being shown thereon in red. If it is to report an issue with the display of an ENC, a screen shot of the affected cell should be sent along with details of the ECDIS make and version in use at the time.

### **Depth Reporting**

6. When soundings are obtained using echo sounders, the echo sounding trace should be duly annotated with date, times, position, depths, etc., and forwarded with the IH102. It is important to state whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name and type of echo sounder should also be given.

7. For modern echo sounders that use electronic 'range gating', care should be taken that the correct range scale and appropriate gate width are in use. Older electro-mechanical echo sounders frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognised by the following:

- (a) the trace being weaker than normal for the depth recorded;
- (b) the trace passing through the transmission line;
- (c) the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from the charted depths. Efforts should be made to identify and negate false echoes if any. The Mariners Handbook (NP100) and Notice 15 Special Edition of Notice to Mariners may be consulted.

8. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be notified.

9. Reports of **shoal soundings**, uncharted dangers and aids to navigation out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers in such that any uncharted depth under 30 meters or 15 fathoms may be of sufficient importance to justify a radio message.

10. Changes to Port information should be forwarded on Form IH.102A together with form IH.102. Form 102 A contains the information required for Sailing Directions and should be used as an *aide memoir*. The Mariners Handbook, NP100, Chapter 8 gives general instructions. Where there is insufficient space on the forms an additional sheet should be used.



*Please Note:* - An acknowledgement will be sent by National Hydrographic Office for Hydrographic Notes received. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless the information is also received from other authorities/foreign Notices to Mariners. Further communication from National Hydrographic Office to the sender of Hydrographic Notes will only be necessary to verify unusual features or abnormal values reported.




<b>HYDROGRAPHIC NOTE</b>				<b>IH.102 (Revised 2012)</b>	
For Forwarding information for Indian Charts, ENC's and Publications and reporting of ENC related issues					
Date		Ref. Number			
Name of the Ship or Sender					
Address					
Tel/FAX/E-mail address					
Observation Date		Time (UTC/IST)			
Object of Changes Observed (Tick appropriate)	<input type="checkbox"/> Bathymetry	<input type="checkbox"/> Nav. Dangers	<input type="checkbox"/> Nav. aids		
	<input type="checkbox"/> Designated Areas	<input type="checkbox"/> Others			
Geographical Position (See Instructions Overleaf)	Latitude		Longitude		
Position Method	<input type="checkbox"/> DGPS	<input type="checkbox"/> GPS	<input type="checkbox"/> Radar	<input type="checkbox"/> Others	
Datum Used	<input type="checkbox"/> WGS84	<input type="checkbox"/> Everest	<input type="checkbox"/> Others		
Charts Affected		Edition			
Latest Edition of Indian Notices to Mariners Held					
Tracing/Plot/Photograph if enclosed					
ENCs Affected					
Latest Update Disk Held					
Publication Affected		Edition			
Page No./Light No. etc					
Details:					
Limitations if any in Reporting the Changes Above					
Details of Documents/Photos attached:					
Signature of the Master/Reporter/Observer					

<b>HYDROGRAPHIC NOTE FOR PORT INFORMATION</b> (To accompany Form IH.102)		<b>IH.102A</b> (Revised 2012)	
Date		Ref. No.	
Name of the Ship or Sender			
Address			
Tel/Fax/E-mail			
<b>1. NAME OF PORT</b>			
Location	Latitude		Longitude
<b>2. GENERAL REMARKS</b>			
Principal activities and trade			
Number of ships and tonnage handled per year			
Maximum size of draught of vessel handled			
Copy of Port handbook (if available)			
<b>3. ANCHORAGES</b>			
Type / Purpose			
Minimum depth at anchorage			
Shelter afforded			
Holding ground			
Recommended pilotage to the anchorage			
<b>4. PILOTAGE</b>			
Authority for request			
Embarkation position			
Regulations			
Documents to be provided			
Recommended pilotage to approach of Harbour and Berths			
Information on VTMS			
<b>5. DIRECTIONS</b>			
Entry and Berthing Information			
Tides (Height)			
Tidal Stream Information			
Wind Speed and Direction			
Navigational Aids (Beacons / Buoys / Lights / Etc.)			
<b>6. POLLUTION CONTROL</b>			
Local regulation in force (If Any)			
<b>7. TUGS</b>			
Number available / Tug type			
Maximum HP / Bollard pull			

<b>7. TUGS (Continued)</b>	
Requesting authority	
Availability timing / Communication	
Hiring charges	
<b>8. BERTHING AND WHARVES</b>	
Type & Number of berths available	
Length	
Depth alongside	
Facilities available	
Procedure for requesting berth & hiring charges	
<b>9. CARGO HANDLING</b>	
Containers	
Lighters & Ro-Ro etc.	
<b>10. CRANES</b>	
Brief details of Max. lifting capacity, Height of boom at wharf level and Outreach	
Container handling facilities	
<b>11. BRIDGES</b>	
Vertical clearance	
<b>12. REPAIRS</b>	
Hull machinery and underwater	
Ship and Boat yards	
Docking or Slipway facilities (Size/ Dimensions of vessels handled)	
Hards and Ramps	
Divers / Diving assistance	
<b>13. SERVICES</b>	
Radio / FAX / Telephone / Internet etc.	
Medical	
Quarantine	
Consul	
Ship chandlery and Stevedores	
Compass adjustment	
Tank cleaning	
Hull painting	
Police / Ambulance / Firefighting (Fixed and Mobile facilities)	
Nav. Warning and Weather bulletin	
Garbage disposal / Waste oil disposal	
Helicopter landing facilities	

<b>14. RESCUE &amp; DISTRESS</b>	
Salvage, Lifeboat, Life guards, etc	
<b>15. SUPPLIES</b>	
Fuel (Type, Quantities & Method of delivery)	
Fresh water (Method of delivery and Rate of supply)	
Provisions	
Chart agents	
<b>16. COMMUNICATIONS</b>	
Road, Rail and Air services available	
Nearest airport or airfield	
Port Radio and Information Service (Frequencies and Operating Hours)	
<b>17. PORT AUTHORITY</b>	
Designation, Address, Telephone, E-mail Address and Website	
<b>18. SECURITY</b>	
Security of ports / International Ship and Port Facility Security (ISPS) compliance	
Custom and Immigration Regulations in force	
<b>19. SMALL CRAFT FACILITIES</b>	
Information and facilities for small craft, yachts visiting the port	
Yacht clubs, berths etc	
<b>20. SHORT LEAVE</b>	
<b>21. CLUBS RECREATION</b>	
Information Kiosk (Location)	
Foreign Exchange firms / Banks (Within / Near Port Area)	
Places of interest near port	
<b>22. VIEWS</b>	
Photographs(Duly annotated) of the approaches, leading marks, the entrance to the harbour etc.	
<b>23. ADDITIONAL DETAILS</b>	
Any other information considered to be useful for the mariners	
<b>SIGNATURE OF THE OBSERVER / REPORTER / MASTER</b>	



**FOR 24 X 7 SAR ASSISTANCE IN INDIAN SRR**

**Email: [indsar@vsnl.net](mailto:indsar@vsnl.net)**

**NATION WIDE SAR TELE: 1554 (LAND LINE)**

**INMARSAT C (IOR) 441907210 CODE: 43 (TOLL FREE)**

**AFTN: VABBYXYC**