

**\*363 (18/02) INDIA– East Coast – Hugli River – Channel buoys**

Amend	S. F. buoy to, <i>Fl. R.(2)10s</i>	(a) 21° 58'.57N, 88° 02'.34E
	MC - V buoy to, <i>Qk Fl</i>	(b) 21° 46'.92N, 88° 03'.46E
	MC - II buoy to, <i>Fl.(3)15s</i>	(c) 21° 49'.80N, 88° 03'.30E
	U.B.S. buoy to, <i>Fl.R. (2)10s</i>	(d) 21° 52'.96N, 88° 04'.68E
Move	Auckland Boat Buoy (A.B.B.), <i>Q.Fl</i> from:	(e) 21° 49'.79N, 87° 59'.85E
	to:	(f) 21° 49'.78N, 87° 59'.68E
	port hand buoy (L.R.), <i>Fl(2)10s</i> from:	(g) 22° 00'.29N, 88° 11'.17E
	to	(h) 22° 00'.513N, 88° 11'.505E
	port hand buoy (L.M.P.), <i>Fl(2)10s</i> from:	(i) 21° 55'.31N, 88° 06'.58E
	to :	(j) 21° 54'.61N, 88° 06'.60E

**Chart** [*Last correction*]: – 3013 (a, g-j) [309/02] – 3011 (b-f, i, j) [309/02]

(Kolkata Port Trust: HJ/1129/11)