

\*230 (11/03) INDIA – West Coast – Port of Mumbai – Buoy

Cancel INM 175 (T)/03 and 226 (P)/03

North Karanja buoy functioning normal.

18° 55'. 12N., 72° 52'. 7E

Charts affected – 2001 [80/03] – 2015(INT7337) [190/03] – 2076 [198/03] – 2016 [198/03] – 211 [216/03]

(Mumbai Port Trust: HJ/1030/87)