

***80 (03/03) INDIA – West Coast – Mumbai Harbour – Buoys**

Cancel former notice 370/02

Insert	Indira Dock channel dam buoy <i>Fl.3s</i>	(a)	18° 56'.05N., 72° 50'.80E.
	▲ (Green) South entrance, <i>Fl.G.5s</i>	(b)	18° 50'.36N., 72° 48'.58E.
Move	↷ (Red) Southwest prong's reef, <i>Fl.R.5s</i>	(c)	18° 51'.27N., 72° 47'.40E.
	↷ Prong's Reef (<i>Fl.(2)R.10s</i>) from:	(d)	18° 51'.44N., 72° 48'.89E.
Delete	to:	(e)	18° 51'.55N., 72° 48'.84E.
	▲ (Green) South entrance, <i>Fl.G.5s</i>	(f)	18° 50'.23N., 72° 47'.86E.
	↷ (Red) Southwest prong's reef, <i>Fl.R.5s</i>	(g)	18° 51'.50N., 72° 47'.70E.

Chart [*Last correction*]: – 2001 (a) [348/02] – 2015 (INT 7337) (a-e)[348/02] – 2016 (b-e) [416/02] – 211 (b-g) [348/02]

(Mumbai Port Trust: HJ/1030/87)