

*** 258/(15/09) INDIA -WEST COAST – Malacca Banks – Buoy.**

Source: Hydrographic Note - MV British Ruby & DLL Jamnagar

(HJ/1130/07)

Chart 254 [*previous update 239/09*]

Amend buoy to : Fl(9)15s

20° 56′·37N, 72° 06′·95E

Chart 207 [*previous update 239/09*]

Amend buoy to : Fl(9)15s

20° 56′·37N, 72° 06′·95E