

**\*208 (T)/(24/14) Myanmar – Yangon River – Buoys.**

Source: Myanmar Hydrographic Department.

1. Eight Navigational buoys have been laid in the following positions to define navigable channel at western channel entrance, Yangon river.

<b>Sl. No.</b>	<b>Buoy Name</b>	<b>Position</b>	<b>Characteristics</b>
*(a)	Intermediate Buoy	16° 23′.600N., 96° 21′.100E.	Fl.G.4s
*(b)	Lower Spit Buoy	16° 24′.400N., 96° 21′.480E.	Fl.G.2s
(c)	Center Spit Buoy	16° 25′.461N., 96° 21′.985E.	Fl.G.3s
(d)	Upper Spit Buoy	16° 26′.600N., 96° 21′.650E.	Q.G
*(e)	Additional Lower Western Buoy	16° 24′.100N., 96° 20′.450E.	Fl.R.4s
*(f)	Lower Western Buoy	16° 24′.810N., 96° 21′.080E.	Fl.R.3s
(g)	Center Western Buoy	16° 25′.583N., 96° 21′.123E.	Fl.R.2s
*(h)	Additional Upper Western Buoy	16° 26′.400N., 96° 20′.580E.	Fl.R.2s

\* Indicates new or revised entries.

2. Vessels entering the harbour are to keep the buoy no (a) - (d) on starboard side, and buoy no (e) - (h) on port side. It is to be vice versa while outgoing to the sea.

3. Mariners to take note and contact local port authorities for more information.

4. ***Former INM 195(T)/14 is cancelled.***

**Chart Affected – 41 (INT 757) – 410 – 411 – 451 – 452 – 4019.**